Vehicle Health Check

CUSTOMER DETAIL

W

Tel

VEHICLE DETAIL

Chassis No

VHC NO 4651

Н

Make Porsche Model 944

Date 2023-06-19

viodei 344

90740

WP0AA0953GN152822

Service Advisor Sam MOT Due

M +971561731797

Registration DXBU-29536

Inspected By Nish

Mileage

	Comments / Recommendations	Net	VAT	Tota
Required				
Check & Report 2 hours				
Battery				
Test & Report				
Other				
Lights	L			
Front Left				
Front Right				
Rear Left	Minor cracks on lens.			
Rear Right	Minor cracks on lens.			
Left Side	Minist Gradito ST 1876.			
Right Side				
Brake				
Reveres				
Front Fog				
Rear Fog				
Report 1				
Report 2				
Other				
nside			1	
Air Conditioning	AC system faulty. 1-control unit faulty, 2-AC compressor leaking.			
Washer Operation				
Warning Lights				
Horn	Horn switch not working properly.			
Seat Belts				
Wipers				
Windscreen				
Window RF				
Window LF				
Window LR				
Window RR				
Door FR				
Door FL				
A Door RR				
A Door RL				
Vents				
Seats				
Switches 1				
Switches 2				
Switches 3				
Switches 4				
Other 1	Speakers broken.			
Other 2				
Other 3				
Other 4			+	1

Rear Boot

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 4651

Service Advisor Sam

н

Make Porsche Model 944 Date 2023-06-19

Tel M +971561731797

Registration DXBU-29536

MOT Due

W

Chassis No WP0AA0953GN152822 Inspected By Nish

Mileage 90740

		Comments / Recommendations	Net	VAT	Total
G	Wiper				
G	Supports 1				
G	Supports 2				
G	Other 1				
G	Other 2				
В	rakes Discs/Pads		,		1
G	Right Front				
G	Left Front				
G	Right Rear				
G	Left Rear				
G	Other				
В	rakes System			1	
G	Brake Cylinders				
G	Fluid Condition				
G	Hoses				
G	Cables				
G	Other				
W	heel Bearings				
Α	Front Right	Front right wheel bearing play. Need to be adjusted.			
Α	Front Left	Front left wheel bearing play. Need to be adjusted.			
G	Rear Right				
G	Rear Left				
G	Other				
S	uspension				I .
G	Roll Bar Front				
G	Steering Joints				
Α	Shock Absorber FL	Shock absorbers old, boots broken and top mount Worn-out.			
G	Ball Joint FL	Chook absorbers sia, books broken and top mount worm out.			
G	FL Lower				
G	FL Upper				
A	Shock Absorber FR	Shock absorbers old, boots broken and top mount Worn-out.			
G	Ball Joint FR	Gridek absorbers did, boots broken and top mount worm out.			
G	FR Lower				
G	FR Upper				
G	Roll Bar Rear				
G	Shock Absorber RR				
G	Ball Joint RR				
G	RR Upper				
G	RR Lower				
G	Shock Absorber LR				
G	Ball Joint LR				
G	LR Upper				
G	LR Lower				
G	Other 1				
G	Other 2				
G	Other 3				
					-
G	Other 4				

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 4651

Service Advisor Sam

Н

Make Porsche Model 944 Date 2023-06-19

Nish

M +971561731797

Registration DXBU-29536

MOT Due

W

Tel

Chassis No WP0AA0953GN152822 Inspected By

Mileage 90740

	Comments / Recommendations	Net	VAT	Total
Subframe				
G Mountings 1				
G Mountings 2				
G Mountings 3				
G Mountings 4				
G Other 1				
G Other 2				
Engine		1		
G Bonnet Supports				
G Drive Belts 1				
G Drive Belts 2				
G Intake Sysytem				
G Intake Sensors 1				
G Intake Sensors 2				
G Intake Sensors 3				
G Fuel Sysytem 1				
G Fuel Sysytem 2				
G Fuel Sysytem 3				
G Fuel Sysytem 4				
G Oil Leaks 1				
G Oil Leaks 2				
G Oil Leaks 3				
G Oil Leaks 4				
G Coolant				
G Coolant 1				
G Coolant 2				
G Coolant 3				
G Coolant 4				
A Other 1	Spark plugs need to be replaced.			
A Other 2	Required engine oil service.			
Exhaust				
G Manifold				
G Catalyst Converter				
G Silencer				
A Mountings	Mount cracked.			
G Tail Pipes				
G Other 1				
G Other 3				
Gearbox				-
A Oil Leaks 1	Oil leak from the gearbox, should clean and recheck.			
G Oil Leaks 2				
G Service				
G Drive Shafts 1				
G Drive Shafts 2				
G Drive Shafts 3				
G Drive Shafts 4				
G Torque Tube/Cardinan Shat	ít l			

Vehicle Health Check

CUSTOMER DETAIL

Tel

VHC NO 4651

Н

Make Porsche 944 Model

Date 2023-06-19

Service Advisor Sam DXBU-29536 **MOT Due**

Registration M +971561731797 W Chassis No WP0AA0953GN152822


Inspected By Nish

90740 Mileage

	Comments / Recommendations	Net	VAT	Total
G Mountings				
G Other 1				
G Other 2				
Covers			•	
G Under Covers 1				
G Under Covers 2				
G Under Covers 3				
G Under Covers 4				
G Other				
Outside				
A Bodywork 1	Small scratches.			
Bodywork 2				
Bodywork 3				
G Bodywork 4				
G Mirrors / Glass 1				
G Mirrors / Glass 2				
G Other 1				
G Other 2				
Other				
G Other 1				
G Other 2				
Road Test				•
A Technicians Comments	Engine mount slightly vibrate.			
	Total	0.00	0.00	0.00

Tyres	Trea	ad (r	nm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	6.1	6.7	6.7	NITTO	205/55 R 16	3420
G N/S Rear	5.9	6.4	6.4	NITTO	225/55 R 16	0120
G O/S Front	6.1	6.6	6.7	NITTO	205/55 R 16	3420
G O/S Rear	6.0	6.2	6.0	NITTO	225/55 R 16	0120
G Spare						

Photos











































Shock Absorber FR - Image 2 of 2



Mountings - Image 1 of 1



Oil Leaks 1 - Image 1 of 2



Oil Leaks 1 - Image 2 of 2



Bodywork 1 - Image 1 of 1



Customer Signature_

The work outlined in this report has been brought to my attention

NOTE... All PRICES ARE IN AED - This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Prices include parts and labour. Estimate valid for 30 days from inspection.