

TECHNICIAN NAME: HASSAN  
 CUSTOMER NAME: NASER  
 VEHICLE NAME: TOYOTA FJ55

DATE:21/11/2024  
 KM: 119178

### INSPECTION REPORT

VIN: FJ55104283

1.	ENGINE OIL	TOPUP
2.	AIR FILTER	NEED TO CLEANING
3.	COOLANT	LEAKING
4.	RADIATOR LOWER HOSE	LEAKING NEED TO REPLACE
5.	GEAR OIL	LEAKING
6.	GEAR OIL	TOPUP
7.	SPEED MOTOR SENSOR (O-RING)	LEAKING NEED TO REPLACE
8.	FRONT CRANK SEAL	LEAKING NEED TO REPLACE
9.	ENGINE OIL SUMP	LEAKING NEED TO REPAIR
10.	DRY NUT	LEAKING NEED TO REPLACE
11.	STEERING BOX	LEAKING NEED TO REPAIR
12.	TIE ROD OUTER&INNER SHOCK BOOTS	BROKEN NEED TO REPLACE
13.	REAR AXLE SEAL	LEAKING NEED TO REPLACE
14.	REAR DIFFERENTIAL	LEAKING NEED TO REPAIR
15.	DIFFERENTIAL OIL	TOPUP
16.	FUEL TANK HOSE *2	LEAKING NEED TO REPLACE
17.	CHASIS BODY BUSH	BROKEN&MISSING, NEED TO REPLACE
18.	FRONT WHEEL CAP*2	MISSNG
19.	ALL WIRES	NEED TO FIX PROPERLY



M10 - Mussafah Industrial Area, Abu Dhabi - U.A.E

0509150800 , 0562525899 @ carlabrepairs@gmail.com

20.	FRONT AND REAR BRAKES	SUPLIMENTRY
21.	FRONT WIPERS AND WIPPER NOZZLE	MISSING
22.	FRONT LEAF BUSH	BROKEN, NEED TO REPLACE
23.	FRONT ROMANA FULL SEAL LIT	LEAKING
24.	REAR LEAF BUSH	BROKEN, NEED TO REPLACE
25.	REAR BRAKE&REVERSE LIGHT	NOT WORKING
26.	PAINTING	RUSTS ON SOME AREA
27.	CONSUMABLES	
28.	LABOUR CHARGES	

**PLEASE NOTE:**

\*ANY OTHER PARTS FOUND NECESSARY TO BE REPLACE DURING THE COURSE OF REPAIR WILL BE CHARGE EXTRA.

\*AFTER FIXED ABOVE MENTIONED JOB THEN HAVE TO DO TEST DRIVE AND NOTIFY TO THE CUSTOMER FINAL REPORT OF VEHICLE.



M10 - Mussafah Industrial Area, Abu Dhabi - U.A.E

0509150800 , 0562525899 @ carlabrepairs@gmail.com