

# As of 06/2006 Mercedes-Benz Vehicle Diagnostic Report

## Vehicle Information

As of 06/2006/Mercedes-Benz/211.077 E 63 AMG/  
VIN: WDBUF77X28B304585

Odometer Reading: 207959 km  
License Plate: --

## Customer Information

Name: --

Tel: --

## Device information

Scanner: MaxiSys MS909  
Version: V5.92

Serial Number: VA9GP3C01223  
Repair Order Number:  
VA9GP3C0122320241214174708909

## System Scanned( 41 )

System	Status/DTC
ECM(Engine Control Unit)	3
TCM(Transmission Control Unit)	0
SRS(Supplemental Restraint System Control Unit)	0
KI(Instrument Cluster)	0
CGW(Central Gateway Control Unit)	0
EZS(Electronic Ignition Lock Control Unit)	0
FSCU-R('Right fuel pump')	0
FSCU-L('Left fuel pump')	0
ESP(Electronic Stability Program Braking System)	0
EWM(Shift Lever Control Unit)	0
ADS(Suspension)	0
DIAG(System diagnosis(CAN))	1
SAM-F(Signal acquisition and actuation module front)	0
SAM-P(Passenger-side signal acquisition and actuation module)	0
SAM-R(Rear Signal Acquisition Control Unit)	1
AHE(Trailer Recognition)	1
UBF(Lower Control Panel)	0

OBF(Upper Control Panel)		✓ 0
PTS(Parking System)	ADAS	✓ 0
DBE(Sunroof Control Unit)		✗ 2
ESED(Driver Side Electric Seat Adjustment Control Unit)		✓ 0
ESEP(Passenger Side Electric Seat Adjustment Control Unit)		✓ 0
TSGVL(Door control module front left)		✓ 0
TSGVR(Door control module front right)		✓ 0
TSGHL(Door control module rear left)		✓ 0
TSGHR(Door control module rear right)		✓ 0
HKS(Trunk Lid Control Unit)		✓ 0
MRM(Steering Column Control Unit)		✓ 0
RBTMFL(Driver Seat Belt Tensioner Control Unit)		✓ 0
RBTMFR(Passenger Seat Belt Tensioner Control Unit)		✓ 0
KLA(Air Conditioner Control Unit)		✓ 0
XALWA-L(Xenon headlamp, left)		✓ 0
XALWA-R(Xenon headlamp, right)		✓ 0
ASSYST(ASSYST)		✓ 0
ASSYST PLUS(ASSYST)		✓ 0
AGW(Audio Gateway Control Unit)		✓ 0
CTEL(Cellular telephone)		✓ 0
NAVI(Navigation Control Unit)		✓ 0
CDW(CDC)		✓ 0
SBS(Voice control system)		✓ 0
TV-TUNER(Analog Tv Processor)		✓ 0

**DTC ( 8 )****ECM(Engine Control Unit) ( 3 DTCs )**

DTC	Description	Status
0750	Self-adaptation of mixture formation for enleanment at idle for the left cylinder bank is below the permissible limit. (P2190)	Stored
0746	Self-adaptation of mixture formation for enleanment at idle for the right cylinder bank is below the permissible limit. (P2188)	Stored
3699	Fuel pressure control : The upper limit value is reached. (P0191)	Stored&Current

**DIAG(System diagnosis(CAN)) ( 1 DTC )**

DTC	Description	Status
930C	Knowledge base configuration incomplete.	Stored

**SAM-R(Rear Signal Acquisition Control Unit) ( 1 DTC )**

DTC	Description	Status
9078	Communication with component H319 (Alarm signal horn) is interrupted.	Stored&Current

**AHE(Trailer Recognition) ( 1 DTC )**

DTC	Description	Status
B1078	Please refer to vehicle service manual.	Stored&Current

**DBE(Sunroof Control Unit) ( 2 DTCs )**

DTC	Description	Status
9087	Sliding roof lining not normalized.	Stored
9068	SR is not normalized. If fault code occurs with no complaint reported and no malfunctions, erase fault memory and perform a function check.	Stored

**Technician Notes**

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.