

# Vehicle Diagnostic Report

The Report is created by **DaTo Tech Co.LTD**

## Repair Shop

Shop Name:

Address:

Zip Code:

Telephone:

Email:

SN: 988150001511

Test Time: 2024-11-28 09:00:13

Technician Name:

Customer Name:

## Vehicle Information

Make: Mercedes-Benz

Model: 215.376 - CL 600

VIN: WDB2153761A031818

Vehicle Software Version: V50.37

Diagnostic Application Version: V1.00.007

Diagnostic path: Automatically Search

## System fault code(Post-Repair)

SRS - Supplemental Inflatable Restraint System 2 problems exist

1.9003	The Supply Voltage Of The Control Unit Is Too Low(Undervoltage).	Stored
2.9023	The Component Or The Signal Line To The Component B48(Front Passenger Seat Occupied And Child Seat Recognition) Has Short Circuit To Ground.	Stored

OCP - Overhead Control Panel 1 problem exist

1.B1066	SR Is Not Normalized.	Stored
---------	-----------------------	--------

PSE - Pneumatic System Equipment 3 problems exist

1.B1440-010	Over The Safety Time:Trunk Lid Remote Unlock	Current
-------------	----------------------------------------------	---------

2.B1442-018	Over Servo Turnoff Safety Time:Trunk Lid	Current
3.B1437	Over The Safety Time Of The Center Lock Device:Lower Or Raise Rear Seat Head Pillow Phneumatic Branch Way	Current
REAR SAM - Rear Signal Acquisition And Actuation Module 1 problem exist		
1.B1617	Component E19/1(Left License Plate Lamp) Is Defective.	Current and stored
IC - Instrument Cluster 1 problem exist		
1.B110E	Fault In CAN Communication With Control Unit Telematic.	Current and stored
SCM - Steering Column Module 2 problems exist		
1.B1331-000	Component S111s3(Accept/terminate Phone Call Pushbutton) Is Defective.	Stored
2.B1333-000	Component S110s3(System Select Pushbutton) Is Defective.	Stored
DCM_FL - Door Control Module Front Left 1 problem exist		
1.B1193-000	[Component S86/2s1(Power Locking Microswitch) Is Closed FOr Longer Than 80 s.] or[Ignore Fault Code And Erase Fault Memory. Component Is Not Installed, or Vehicle Equipment Is Wrongly Coded.( Closing Assist Of Doors )]	Stored
DCM_FR - Door Control Module Front Right 1 problem exist		
1.B1193-000	[Component S87/4s1(Power Locking Microswitch) Is Closed FOr Longer Than 80 S.]Or[Ignore Fault Code And Erase Fault Memory. Component Is Not Installed, or Vehicle Equipment Is Wrongly Coded.( Closing Assist Of Doors )]	Stored
AC - Air Conditioning 1 problem exist		
1.B1000	Control Unit N22(AAC Pushbutton Control Module) Is Defective	Stored
The following systems are OK:		
1.TCM - Transmission Control Module		
2.ESM - Electronic Selector Module		
3.ECM - Engine Control Module(ME)		
4.ESP - Electronic Stability Program		
5.ABC - Active Body Control		
6.CGW-Central Gateway		
7.EIS - Electronic Ignition Switch ELCODE		
8.HLCM_L_Left Headlamp Control Module		
9.HLCM_R_Right Headlamp Control Module		
10.UCP - Upper Control Panel		
11.SAM_FL - Front Left Signal Acquisition And Actuation Module		
12.SAM_FR - Front Right Signal Acquisition And Actuation Module		

13.System Diagnosis(Only Interior CAN Fault)

14.PTS - PARKTRONIC

15.AGW - Audio Gateway(MOST Network Management, Diagnosis Gateway, Radio Tuner)

16.ESA\_FL - Electric Seat Adjustment Front Left

17.ESA\_FR - Electric Seat Adjustment Front Right

18.OSB\_FL - Multicontour Backrest Front Left

19.OSB\_FR - Multicontour Backrest Front Right