



## Tax Invoice

Bill To Andrew Deane

Mobile (056) 442-7595

Invoice # 1120  
 Work Order # 1028  
 Service Advisor Mohammed Cassim  
 Technician Hans

Plate DXB 0 6798  
 Description Red 1976 Mercedes Benz 450 SI  
 VIN 10704412035336  
 Odometer 99,205 In / 99,278 Out  
 Invoice Date 01/04/2024 12:00 PM

### Service

#### Retro Fit Radio

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Radio	1 Unit	2,469.63 / Unit	2,469.63 V
Shipping	1 Unit	172.75 / Unit	172.75 V
Labor			1,000.00 V
			<b>Sub 3,642.38</b>

#### Inspect & Diagnose Oil Leak

Diagnostic Charge - Charge Removed In Discount Section

350.00 V

**Sub 350.00**

#### Power Steering Pump

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Power Steering Pump	1 Unit	2,377.33 / Unit	2,377.33 V
Shipping	1 Unit	840.64 / Unit	840.64 V
Customs	1 Unit	225.26 / Unit	225.26 V
Power Steering Fluid	2 Unit	95.00 / Unit	190.00 V
Consumables	2 Unit	25.00 / Unit	50.00 V
Labor			1,225.00 V
			<b>Sub 4,908.23</b>

#### Replace Steering Coupler

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Steering Coupler	1 Unit	244.93 / Unit	244.93 V
Shipping	1 Unit	231.13 / Unit	231.13 V
Customs	1 Unit	33.32 / Unit	33.32 V
Consumables	2 Unit	25.00 / Unit	50.00 V
Labor			973.00 V
			<b>Sub 1,532.38</b>

#### Recovery Charge

Tow Charge from DT To AL Manara (20.01.24)

1 Unit 150.00 / Unit 150.00 V

Tow Charge from Jumeirah to DT(22.01.24)

150.00 V

**Sub 300.00**

#### Starter Motor

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Starter Motor Repair	1 Unit	725.00 / Unit	725.00 V
Labor - Reduced Rate			375.00 V
			<b>Sub 1,100.00</b>

**Towing**

## Tow Vehicle

Tow Charge (19.02.24)			350.00 V
DT to RTA			
RTA to DT			

<b>Sub</b>	<b>350.00</b>
------------	---------------

**Fuel Pump**

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor			350.00 V
Fuel Pump	1 Unit	150.00 / Unit	150.00 V

<b>Sub</b>	<b>500.00</b>
------------	---------------

**Fuel Top-up**

Fuel Top-up (02.01.24)			158.77 V
(For El Camino Before Returning To Customer Home on PREVIOUS VISIT)			

Fuel Top-up (10.02.24)	1 Unit	100.00 / Unit	100.00 V
Fuel Top-up (22.03.24)			100.00 V

<b>Sub</b>	<b>358.77</b>
------------	---------------

---

Total Parts	8,009.99
Total Labor	4,273.00
Total Sublet	758.77
Total Before Taxes & Miscellaneous Charges	13,041.76

(D) Discount*	( 350.00)
(V) VAT 5%*	582.09

<b>Grand Total</b>	<b>13,273.85</b>
--------------------	------------------

Thank you for your business!

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Andrew Deane paid 3,642.39 by Deposit (Payment Link)

Andrew Deane paid 3,700.00 by Deposit (Payment Link)

Andrew Deane paid 5,931.46 by Payment Link

**Customer Signature:** \_\_\_\_\_