



JOB CARD / WORK ORDER

Customer : ANDREW DEANE Address : Tel. No. : Contact : ANDREW DEANE	Email : Fax : Mob. : 0564427595	Job No. : MC-9682 Date : 01/04/2022 13:01 Est. No. : TRN : NA Location : Dubai										
Vehicle : MERCEDES BENZ Model : 450 SL Chassis No. : 10704412035336 Engine No. :	Reg. No. : 0 6798 DXB Year : 1976 Color : RED Kms : 98,599	<table border="1"> <thead> <tr> <th colspan="2">-----CHARGES-----</th> </tr> </thead> <tbody> <tr> <td>Labor</td> <td>: AED 350.00</td> </tr> <tr> <td>Spare Parts</td> <td>: AED 160.00</td> </tr> <tr> <td>Other Charges</td> <td>: AED 0.00</td> </tr> <tr> <td>TOTAL</td> <td>: AED 510.00</td> </tr> </tbody> </table>	-----CHARGES-----		Labor	: AED 350.00	Spare Parts	: AED 160.00	Other Charges	: AED 0.00	TOTAL	: AED 510.00
-----CHARGES-----												
Labor	: AED 350.00											
Spare Parts	: AED 160.00											
Other Charges	: AED 0.00											
TOTAL	: AED 510.00											
Insurance : Policy No. :	Claim Type : No Claim Claim No. :											
Expected Delivery Date : 01-Apr-2022		Completed Date : 06-Apr-2022										
Inspection List : <table style="display: inline-table; vertical-align: top;"> <tr> <td><input type="checkbox"/> Tools</td> <td><input type="checkbox"/> Antenna</td> <td><input type="checkbox"/> Wheel Caps</td> </tr> <tr> <td><input type="checkbox"/> Jack</td> <td><input type="checkbox"/> Register</td> <td><input type="checkbox"/> Spare Tyre</td> </tr> <tr> <td><input type="checkbox"/> C Lighter</td> <td><input type="checkbox"/> Wipers</td> <td><input type="checkbox"/> Radio</td> </tr> </table>			<input type="checkbox"/> Tools	<input type="checkbox"/> Antenna	<input type="checkbox"/> Wheel Caps	<input type="checkbox"/> Jack	<input type="checkbox"/> Register	<input type="checkbox"/> Spare Tyre	<input type="checkbox"/> C Lighter	<input type="checkbox"/> Wipers	<input type="checkbox"/> Radio	
<input type="checkbox"/> Tools	<input type="checkbox"/> Antenna	<input type="checkbox"/> Wheel Caps										
<input type="checkbox"/> Jack	<input type="checkbox"/> Register	<input type="checkbox"/> Spare Tyre										
<input type="checkbox"/> C Lighter	<input type="checkbox"/> Wipers	<input type="checkbox"/> Radio										
<input type="checkbox"/> Warranty Date :												

JOB CARD DETAILS

SERVICES

SI No.	Description	Amount
1	DIAGNOSE WEIRD STAGGERED MOVEMENT OF THE SPEEDOMETER NEEDLE - SPEEDOMETER SPEED INCREASING IN THE INCREMENT OF 5 INSTEAD OF MOVING SMOOTHLY. ATTEMPT TO REMOVE CARD FELL DOWN DASHBOARD WINDSHIELD VENT	AED 350.00
		AED 350.00

MISCELLANEOUS

SI No.	Description	Qty	Price	Amount
1	RECOVERY	1.000	AED 160.00	160.00
				160.00

Net Amount : **AED 510.00**

TRN : 100390070900003

VAT 5% : AED 25.50

TOTAL : Five Hundred Thirty-Five Dirhams And Fifty Fils Only.

AED 535.50

Narration :

Customer Complaints :

REMOVE THE CARD THAT ACCIDENTALLY FELL INTO DASHBOARD WINDSHIELD VENT

Workshop Remarks :

MOHAMMED CASSIM KOKATAY

For Deutsche Technik

(Customer's Signature)