



# ACCIDENT HISTORY YELLOW BOOK

BESOJI FZ-LLC, IN5 TECH, MEDIA CITY

+971 56 817 8171 HELLO@BESOJI.COM



Date	Time
Saturday, May 25, 2024	09:00 AM

### **Vehicle Details**

MROBU8CD7M0094363

venicie Details		
Make	Model	Year
TOYOTA	Hilux	2021
Engine Size	Mileage (KM)	Fuel Type
6-Cylinder	23405	Petrol
Regional Specs	Transmission	Interior
GCC	Automatic	Fabric
VIN Number	Number of Keys	Spare Tire

Available

# **Engine**

**Drive Belt / Pulleys Hoses & Pipes Engine Upper Cover** Pass Pass Pass **Bonnet Hinge & Holder Engine Oil Level Engine Oil Filler Cap** Pass Pass Pass **Coolant Cap Coolant Level Engine Idle** Pass Pass Minor noise from engine vacuum valve **Battery Condition Fender Liners** Pass

# **Electrical System**

Key Remote	Windows Operation	Center Console Buttons
Pass	Pass	Pass
A/C Control & Cooling	Cameras	A/C Grilles
Pass	Pass	Pass
Starting & Ignition System	Brake Lights	Headlights
Pass	Pass	Pass
Fog Lights	Indicators & Hazards	Sunroof / Moonroof
Pass	Pass	N/A
Interior Lights	Rear View / Side Mirror Electricals	
Pass	Pass	

# **Brake System & Tyres**

**Brake Discs Front** 

Pass

Handbrake

Pass

**Brake Discs Rear** 

Pass

**ABS Sensors** 

Pass

## Rims

	Brand	Condition
Front Left	Arctic trucks	Good
Front Right	Arctic trucks	Good
Rear Left	Arctic trucks	Good
Rear Right	Arctic trucks	Good
Spare		

## **Interior**

#### **Roof Lining**

Pass

#### **Rear View Mirror**

**Armrest & Side Pockets** 

Pass

#### **Steering Wheel Upholstery**

Pass

#### **Seats Upholstery**

**Pass** 

**Pass** 

#### **Gear Lever**

**Pass** 

#### **Floor Mats**

Dirty

## **Trunk Lining**

Pass

#### **Dashboard**

Pass

#### **Front Windscreen**

Pass

#### **Rear Windscreen**

Pass

#### **Doors**

Dirty

#### **Floor Mats Fault**



#### **Door Faults**



IMG\_20240525\_095750.jpg



IMG\_20240525\_103712.jpg

# **Service History & Manuals**


**Service History** 

**User Manual** 

Available

Available






Damage on Chassis / Subframe:

PASS

# **Exterior Condition Report**

## **Paint Condition**



#### **Exterior Faults**



IMG\_20240525\_100104.jpg

## **Vehicle Diagnostic Report**

#### **Click Below To Download**



Toyota(DTC)\_989350001593\_20240525102205.pdf

#### **Terms of Service**

All services from BeSoji are provided on an "as is, with all defects" and "as available" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose. Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services.

The inspection of the vehicle described in this report is external and we are unable to accept responsibility for failure to identify defects not present or apparent at the time of the inspection. Odometer readings may have been tampered with, although we report any signs that we notice of this happening during inspection. You acknowledge, by your use of the services, that such use is at your sole risk. In the event of dissatisfaction or a complaint, we reserve the right to re-examine the vehicle prior to any rectifications to the vehicle. You agree that BeSoji's liability is limited to refunding the price you pay for the inspection in the event you are dissatisfied with BeSoji's service, or injuries occur due to an unreported defect in the vehicle. All requests should be sent to hello@besoji.com within 7 days notice of receiving the report.

in no event shall either BeSoji or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages.