



www.BeSoji.com



ACCIDENT HISTORY YELLOW BOOK

BESOJI FZ-LLC,
IN5 TECH, MEDIA CITY

+971 56 817 8171
HELLO@BESOJI.COM

**Date**

Sunday, June 30, 2024

Time

10:00 AM

Vehicle Details**Model**

Grenadier ineos

Year

2023

Engine Size

6-Cylinder

Mileage (KM)

11782

Fuel Type

Petrol

Regional Specs

GCC

Transmission

Automatic

Interior

Fabric

VIN Number

SC6GM1BA5PF005007

Number of Keys

2

Spare Tire

Available

Engine

Engine Upper Cover

Pass

Drive Belt / Pulleys

Pass

Hoses & Pipes

Pass

Bonnet Hinge & Holder

Pass

Engine Oil Level

Pass

Engine Oil Filler Cap

Pass

Coolant Level

Pass

Coolant Cap

Pass

Engine Idle

Pass

Fender Liners

Pass

Battery Condition



Electrical System

Key Remote

Pass

Windows Operation

Pass

Center Console Buttons

Pass

A/C Control & Cooling

Pass

Cameras

Pass

A/C Grilles

Pass

Starting & Ignition System

Pass

Brake Lights

Pass

Headlights

Pass

Fog Lights

Pass

Indicators & Hazards

Pass

Sunroof / Moonroof

Pass

Interior Lights

Pass

Rear View / Side Mirror Electricals

Pass

Brake System & Tyres

Brake Discs Front

Pass

Brake Discs Rear

Pass

Handbrake

Pass

ABS Sensors

Pass

Rims

| | Brand | Condition |
|-------------|----------|-----------|
| Front Left | Original | Good |
| Front Right | Original | Good |
| Rear Left | Original | Good |
| Rear Right | Original | Good |
| Spare | Original | Good |

Interior

Roof Lining

Minor dirty

Rear View Mirror

Pass

Armrest & Side Pockets

Pass

Steering Wheel Upholstery

Pass

Seats Upholstery

Pass

Gear Lever

Pass

Floor Mats

Pass

Trunk Lining

Pass

Dashboard

Pass

Front Windscreen

Pass

Rear Windscreen

Pass

Doors

Pass

Roof Lining Fault



[IMG_20240630_102824.jpg](#)

Service History & Manuals


Service History

Available

User Manual

Available

BeSoji Chassis Damage Report



Damage on Chassis / Subframe:




PASS

Exterior Condition Report

Paint Condition

BeSoji
Exterior Condition Report

- Scratch
- Chip
- Dent
- Accident Paint
- Cosmetic Paint
- Faded



Exterior Faults



IMG_20240630_110435.jpg

Vehicle Diagnostic Report

Click Below To Download



[Mercedes\(DTC\)_989350001593_20240630110310.pdf](#)

Terms of Service

All services from BeSoji are provided on an "as is, with all defects" and "as available" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose. Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services.

The inspection of the vehicle described in this report is external and we are unable to accept responsibility for failure to identify defects not present or apparent at the time of the inspection. Odometer readings may have been tampered with, although we report any signs that we notice of this happening during inspection. You acknowledge, by your use of the services, that such use is at your sole risk. In the event of dissatisfaction or a complaint, we reserve the right to re-examine the vehicle prior to any rectifications to the vehicle. You agree that BeSoji's liability is limited to refunding the price you pay for the inspection in the event you are dissatisfied with BeSoji's service, or injuries occur due to an unreported defect in the vehicle. All requests should be sent to hello@besoji.com within 7 days notice of receiving the report.

In no event shall either BeSoji or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages.