



**PRE-PURCHASE
YELLOW BOOK**

BESOJI FZ-LLC

IN5 TECH, MEDIA CITY

+971 56 817 8171

HELLO@BESOJI.COM



Type Of Inspection

Comprehensive Inspection

Date

Saturday, December 21, 2024

Time

04:00 PM

Vehicle Details

Make

NISSAN

Model

GTR

Year

2000

Engine Size

6-Cylinder

Mileage (KM)

35871

Fuel Type

Petrol

Regional Specs

Japanese

Transmission

Manual

Interior

Leather

VIN Number

BNR34400168

Number of Keys

1

Spare Tire

Available

Service History

Not Available

User Manual

Available

Vehicle Summary

We've explained **some** of the faults below.
Please refer to the full report for all the faults.

Inspector Comments

Car has accident paint.

The diagnosis could not be done because OBD port not responding.

Suspension wear and tear.

Entertainment screen in Japanese language.

Test drive not done as the car is not registered.

Minor underbody rust found.

Left door windows motor slow response.

Repair cost ranges are general and not final. We offer these estimates to provide you more clarity on deciding if you should buy the car or not. These estimates may vary depending on the vehicle make and model, current labor rates, time period issue is present and the complexity of the repair.

Engine Upper Cover

Pass

Engine Shield Cover

Pass

Engine Mounts

Pass

Engine Oil Condition

Pass

Engine Oil Leaks

Pass

Engine Oil Filler Cap

Pass

Coolant Level

Pass

Coolant Cap

Pass

Turbo / Supercharger

Pass

Visible Rust

Minor underbody rest found

Exhaust System

Pass

Engine Idle

Pass

Visible Rust Fault - Photo



IMG_20241221_1633...



196_IMG_20241221_...



IMG_20241221_1633...



IMG_20241221_1627...



IMG_20241221_1627...



IMG_20241221_1626...



IMG_20241221_1627...



196_IMG_20241221_...

Bonnet Hinge & Holder

Pass

Fender Liners

Pass

Drive Belt / Pulleys

Pass

Hoses & Pipes

Pass

Radiator

Pass

Battery Condition ⚡ ⚡ ⚡ ⚡ ⚡

Fluid Level & Condition

No Dipstick Available To Check

Transmission Fluid Leaks

Pass

Gear Selector

Pass

Gear Shifting

Pass

Noise

Pass

Please review the car diagnostic report at the end of this document for more information on the transmission condition.

Key Remote

Pass

Entertainment System

Aftermarket screen in Japanese language. Performance information screen damage.

Entertainment System Fault



IMG_20241221_1652...



IMG_20241221_1652...

Center Console Buttons

Pass

Door Lock / Unlock

Pass

Cameras

Pass

Cruise Control

N/A

A/C Control & Cooling

Pass

Starting & Ignition System

Pass

Gauges

Pass

Fog Lights

Pass

Headlights

Pass

Brake Lights

Pass

A/C Grilles

Pass

High Beams

Pass

Reverse Lights

Pass

Number Plate Lights

Pass

Indicators & Hazards

Pass

Soft Closing Doors

N/A

Wipers

Pass

Interior Lights

Pass

Sunroof / Moonroof

N/A

Windows Operation

Left door windows motor slow.

Seats Adjustment

Pass

Rear View / Side Mirrors

Pass

Windows Operation Fault



IMG_20241221_1733...

Horn

Pass

Parking Sensors Fault

Pass

Brake Pads Front

Pass

Brake Discs Front

Need to skim

ABS Sensors

Pass

Front Suspension

Right side steering boot leaking,

Front Suspension Fault - Photo



[289_IMG_20241221_162539_2935.jpg](#)

Brake Pads Rear

Pass

Brake Discs Rear

Pass

Handbrake

Pass

Rear Suspension

Rear stabilizer bush damage, shock mount cracked.

Rear Suspension Fault - Photo



[290_IMG_20241221_164200_5191.jpg](#)



[IMG_20241221_164228.jpg](#)



290_IMG_20241221_164302_9520.jpg



290_IMG_20241221_164025_1551.jpg

Rims

	Brand	Condition
Front Left	Aftermarket	Good
Front Right	Aftermarket	Good
Rear Left	Aftermarket	Good
Rear Right	Aftermarket	Good

Tyres

	Manufacturer	Date	Size	Condition
Front Left	Bridgestone potenza	2020	275/30R19	5/7mm dry cracks
Front Right	Bridgestone potenza	2020	275/30R19	5/7mm dry cracks

	Manufacturer	Date	Size	Condition
Rear Left	Bridgestone potenza	2020	275/30R19	5/7mm dry cracks
Rear Right	Bridgestone potenza	2020	275/30R19	5/7mm dry cracks

Roof Lining

Pass

Rear View Mirror

Pass

Armrest & Side Pockets

Pass

Steering Wheel Upholstery

Pass

Seats Upholstery

Pass

Gear Lever

Pass

Floor Mats

Pass

Trunk Lining

Pass

Dashboard

Pass

Front Windscreen

Pass

Rear Windscreen


Pass

Doors

Pass



Chassis, Subframe & Internal Damage Report



Damage on Chassis / Subframe:

PASS

General Exterior Photos



IMG_20241221_1521...
319.09 KB



IMG_20241221_1521...
341.21 KB



IMG_20241221_1521...
378.2 KB



IMG_20241221_1521...
362.65 KB



IMG_20241221_1521...
392.74 KB



IMG_20241221_1521...
300.48 KB



IMG_20241221_1521...
286.21 KB



IMG_20241221_1521...
341.44 KB



IMG_20241221_1521...
362.23 KB



IMG_20241221_1523...
356.29 KB



IMG_20241221_1523...
338.31 KB



IMG_20241221_1523...
307.23 KB



IMG_20241221_1523...
333.53 KB



IMG_20241221_1524...
370.34 KB



IMG_20241221_1524...
332.07 KB



IMG_20241221_1524...
316.71 KB



IMG_20241221_1524...
365.82 KB



WhatsApp Image 202...
161.57 KB



IMG_20241221_1526...
435.54 KB



IMG_20241221_1526...
433.57 KB



IMG_20241221_1526...
467.35 KB

Interior Photos



IMG_20241221_1524...
417.28 KB



IMG_20241221_1524...
353.18 KB



IMG_20241221_1524...
341.16 KB



IMG_20241221_1524...
379.16 KB



IMG_20241221_1524...
341.13 KB



IMG_20241221_1524...
434.01 KB



IMG_20241221_1525...
403.96 KB



IMG_20241221_1524...
317.73 KB



IMG_20241221_1525...
315.52 KB



IMG_20241221_1525...
398.47 KB



IMG_20241221_1525...
384.92 KB



IMG_20241221_1525...
367.47 KB



IMG_20241221_1525...
338.18 KB



IMG_20241221_1525...
370.88 KB



IMG_20241221_1530...
405.01 KB

WE JUST OUTPERFORMED YOUR INSURANCE BROKER

We've built the insurance experience from the ground up!

- Get Car Insurance Without Talking To A Human - For The First Time Ever!
- Lowest quotes, transparent pricing, instant cover available 24/7. Policy issued to RTA in 3 minutes.

TRY THE MAGIC



Terms of Service

All services from BeSoji are provided on an "as is, with all defects" and "as available" basis without warranties of any kind, either expressed or implied, including without limitation, warranties of title, non-infringement, or implied warranties of merchantability or fitness for a particular purpose. Nothing in these terms or in any description of products or services in the services shall constitute a representation or warranty with respect to such products or services.

The inspection of the vehicle described in this report is external and we are unable to accept responsibility for failure to identify defects not present or apparent at the time of the inspection. Odometer readings may have been tampered with, although we report any signs that we notice of this happening during inspection. You acknowledge, by your use of the services, that such use is at your sole risk. In the event of dissatisfaction or a complaint, we reserve the right to re-examine the vehicle prior to any rectifications to the vehicle. You agree that BeSoji's liability is limited to refunding the price you pay for the inspection in the event you are dissatisfied with BeSoji's service, or injuries occur due to an unreported defect in the vehicle. All requests should be sent to hello@besoji.com within 7 days notice of receiving the report.

in no event shall either BeSoji or its affiliates or agents be liable for any direct, indirect, punitive, incidental, special or consequential damages arising out of or in any way connected with the use of the services, whether based on contract, tort, strict liability or otherwise, even if advised of the possibility of any such damages.